




Mercedes PowerShift Shafts

Starting from the next few days, the shafts for Mercedes PowerShift gearboxes will be managed **only complete with the relative lubrication ring**, which has been essential for correct assembly since 2002.

The part numbers of the supplied shafts without the lubrication ring will **no longer be orderable**, instead it will be possible to order the lubrication ring code 09400400026 as a spare part.

Please take note of the new codes to be used as summarised in the table below:

WAS				BECOMES	
Article	Description		Ring	Replacement item	Description
09301600015	ALB.COR.MERC.G131/G330 *ISO7707A	+	09400400026	=	09391600150 ALB.COR+LUB MERC.G131/G330
09301600024	ALB.COR.MERC.G131/G330+RET*ISO7707A				09391600249 ALB.COR+LUB MERC.G131/G330+RETARDER
09301600033	ALB.COR.MERC.G281-12 POWERSHIFT 3				09391600338 ALB.COR+LUB MERC.G281-12 POW.SHIFT3
09301600042	ALB.COR.MERC.G281-12 P.SHIFT3+AQUAT				09391600427 ALB.COR+LUB G281-12 P.SHIFT3+AQUAT.
					



Link:
[Data sheet](#)
[Mounting instructions](#)

The sales department is at your disposal for any clarifications.