

ATTENZIONE!

ATTENTION!

**CODICE
CODE**

101050

FUNZIONALITÀ DI SICUREZZA

Il ricevitore, dopo 20 minuti di inutilizzo, si pone automaticamente in stato di emergenza.

SECURITY FEATURE

The receiver, after 20 minutes of non-use, is in a state of emergency.

pag.1



O.M.F.B. S.p.A. Hydraulic Components
We reserve the right to make any changes without notice.
Edition 2011.05 No reproduction, however partial, is permitted.
Via Cave, 7/9 25050 Provaglio d'Iseo (Brescia) Italy Tel.: +39.030.9830611
Fax: +39.030.9839207-208 Internet:www.omfb.it e-mail:contatti@omfb.it

ATTENZIONE!

ATTENTION!

**CODICE
CODE**

101050

FUNZIONALITÀ DI SICUREZZA

Il ricevitore, dopo 20 minuti di inutilizzo, si pone automaticamente in stato di emergenza.

SECURITY FEATURE

The receiver, after 20 minutes of non-use, is in a state of emergency.

pag.1



O.M.F.B. S.p.A. Hydraulic Components
We reserve the right to make any changes without notice.
Edition 2011.05 No reproduction, however partial, is permitted.
Via Cave, 7/9 25050 Provaglio d'Iseo (Brescia) Italy Tel.: +39.030.9830611
Fax: +39.030.9839207-208 Internet:www.omfb.it e-mail:contatti@omfb.it